

# Oil Field Environmental Incident Summary

**Incident:** 20160502085437

**Date/Time of Notice:** 05/02/2016 08:54

**Responsible Party:** Landtech Enterprises LLC

**Well Operator:** LANDTECH ENTERPRISES, LLC

**Well Name:** Locken SWD 1

**Field Name:** SANISH

**Well File #:** 90132

**Date Incident:** 5/1/2016

**Time Incident:** 05:00

**Facility ID Number:**

**County:** MOUNTRAIL

**Twp:** 153

**Rng:** 91

**Sec:** 11

**Qtr:** SW SW

**Location Description:**

**Submitted By:** John Petz

**Received By:**

**Contact Person:** Kirk Johnson  
PO Box 1560  
856 Cambrian Lane  
Sidney, MT 59270

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:** 5280 Feet

**Distance Nearest Water Well:** 5280 Feet

**Type of Incident:** Equipment Failure

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	60	Barrels	60	Barrels		

**Description of Other Released Contaminant:**

Junk fluid/pit water

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none

**Areal Extent:**

**Potential Environmental Impacts:**

none

**Action Taken or Planned:**

Isolated the tanks and put a tub under the leaky valve. Called Power Fuels vac truck to suck up the fluid. Everything was done within 3 hours. Landtech crew will take 2 bobcats out today to clean up contaminated soil and replace new soil. The contaminated soil will be placed in a diked area and then hauled off location.

**Wastes Disposal Location:** Foss SWD

**Agencies Involved:** NDIC - Scott 701-720-5660

**Updates**

---

**Date:** 5/2/2016      **Status:** Reviewed - Assigned to Other Agency

**Author:** O'Gorman, Brian

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to equipment failure, remained within diking according to the report. NDIC retains oversight.